

FOR ROTAX 2-STROKE AND 4-STROKE AIRCRAFT ENGINES

EDITION: 2020 07 01 | PART NO.: 898023



1										2
Engine Log	Book No.:	119	109-644		fo	or pi	ston en	ngine		
Type of engine:	912		Model:	S3-01			Engine s	serial no.:	9.140	0.117
Manufacturer:	BRP-Rotax G A-4623 Gunsk	national species					Year of n	nanufacture	09.05.	2022
Data sheet:	EASA.E.121	<u>.</u>								
Take off power:		73,5	kW	perm. du	ıration:	5	min.	at:	5800	r.p.m
Max. cont. power	er:	69	kW	at:	55	00	r.p.m.			
accordance wo	vith the Civil i nd maintenai Airworthiness	Aircraft a nce instr Directiv	and Civil Avia ructions. res (AD) see	be operationally ation Equipmen EASA Website	: Order,	curi	rent issu	e and the	pertinent	.
Remarks:				red without gov	ernor.					
For Instruction -912-021,SL-91 Engines webs	14-019 List of A	Applicable	hiness (ICAs) i e Publications	like e.g. relevant s for ROTAX Aircra	Service L ft Engin	Bullet es an	tins etc. s nd its refe	ee the curr rence to RO	ent SL-2ST DTAX® Airc	T-013,SL craft
							BF	P-Rotax Gm	0006 CoK	1.78
Date:	16.05.2022				Signatu	ле:	R. Fr	einter of re	eg_314	20

Engine installation record:

,	Aircraft:	Dat	te:	Engine	hours:	Signature &
Registr.:	type:	in:	out:	TSN	TSO	Licence no.:
N-C 918	(2008 JE S/N 1256	15/06/2022		0.0		TECNAM IT. 21 G. 0832
				9		
						9
			*			
					*)	\$ 199 ₆
						.TW

5 S	SB-Status		
Status of Airworthiness I	Directives or modifications effective at 0 hours and at the time of production.	Date:	Signature & Licence no.:
applicable SB: 912-03 optional SB: 912-03 not applicable:	33, 912-042r1, 912-057r1. 37r1.	16. 05. 2022	
912-022, 912-028r1, 9 -045, 912-046, 912-04 -056r1, 912-058, 912-	912-029r3, 912-030r1, 912-031, 912-039, 912-040r1, 912-041r2, 912-043r2, 912 17, 912-048, 912-049, 912-051, 912-052r4, 912-053, 912-054, 912-055, 912 059, 912-060, 912-061r1, 912-062r2, 912-063r1, 912-064r1, 912-066r1, 912 2-071, 912-073, 912-074, 912-075.	-Rotax (G.0006 G.0006 31420
2007-0025: Engine — Crank 2007-0060R1-E: Engine Fuel 2007-0155: Engine Fuel and 2011-0224-E: Engine — Cran 2011-0067-E: Ignition — Ma 2012-0019-E: Engine Fuel 2012-0097R1: Engine Fuel 2013-0117-E: Engine — Cyli installed part number not a 2015-0240: Engine — Engine	gnetic Plug - Inspections; Note: not applicable (unlisted engine serial number) ccase — Inspections; Note: not applicable; (unlisted engine serial number and crankcase) el and Control - Fuel Pump — Replacement; Note: not applicable (unlisted fuel pump) d Control - Coolant Specification — Modification; Note: adjusted manuals nkshaft — Inspection; Note: not applicable (unlisted crankshaft) agneto Flywheel Hub Washer — Replacement; Note: not applicable (unlisted engine serial number) Oil Pump and Attachment Bolts — Inspection; Note: not applicable (unlisted engine serial number) and Control — Fuel Pump Pressure Side Hose — Replacement; not applicable (unlisted fuel pump) inder Head Section — Inspection / Replacement; Note: not applicable (unlisted cylinder head -	16. 05. 2022	
2017-0208; ATA 72 – Reciping affected;	rocating Engine – Valve Push Rod Assembly – Inspection / Replacement; Note: installed parts are <u>not</u> BR R. Fr	P-Rotax AT2	Gmb/ & Coke G.0006 31420

Modification record:

TSN:	Date:	Signature & Licence no.:
Ø	21/6/17	0//
		17//
25		
	2	
		Δ.
	TSN:	TSN: Date:

7		N	Maintenance record	
Date:	Engine	e hours:	Work performed:	Signature &
	Total: TSN:	since last overhaul: TSO:		Licence no.:
16.05.2022	0	-	Individual examination performed	BRP-Rotax GmbH & CoK
			H	R. Freinsen fines 31420
. x				¥ ×
			T T	Ф
9		, =		
4		12 20	ST ST	
	5	n s s		
		*1	×	
	R .	ià	2) 2 —	
	a		×	9 #
	^		•	0
		22		
9		. B	. 1	3 % ₁
à	61		A	1.0
		A		0

Maintenance record:

	Engine	hours:	Mante a sufaves a de	Signature & Licence no.:
Date:	TSN:	TSO:	Work performed:	



luciano sorlini spa

MOTORE / ENGINE:

ROTAX 912S2-01

S/N 9140117

OPERAZIONI ESEGUITE / WORK: REV / WORK REPORT N°.: 2752 GEARBOX MOD. FROM S3 TO S2 & INST. SUSP, FRAME ASSY

DATA: 13.06.2022

ORE T.S.N. 00.00

OPERAZIONI ESEGUITE / PERFORMED WORKS: GEARBOX MODIFICATION FROM S3 TO S2 AND INSTALLATION OF ENGINE SUSPENSION FRAME ASSY I.A.W. ROTAX M.M.H. 899603 AND WORK REPORT 2752 OF SORLINI

P.A. E BOLLETTINI COSTRUTTORE APPLICATI / A.D. AND ROTAX S.B.

2011-0224-E

ON CRANKSHAFT NOT AFFECTED

2012-0097R1

ON NEW FUEL PUMP NOT AFFECTED ON CYLINDER HEADS NOT AFFECTED

2013-0117E 2016-0144

ON FLOATS NOT AFFECTED

2017-0208

ON PUSH RODS NOT AFFECTED

SI-912-031 R1

PERF. GEARBOX MODIFICATION FROM S2 TO S3

Release to Service

Certified that unless otherwise specified the works specified above was accomplished in accordance with Part 145 and in respect to that work the engine is considered ready for release to service

ing. ALBERTO COMINCIOLI C.I.T.NR, C\$100413

